

Description	Prod.-No.	RB 35 B Piccolo 35/50 X	RB 50 X 40 RL-E	RB 80 X 60 RL-E	100 RL-E	Figure
Quick-release tool holder Rota-Quick® • Morse taper 2 • with automatic internal cooling • suitable for all machines with drill spindle MK 2 • Application range to 40 mm core drill Ø	18650	-	✓	✓ With reducing sleeve MK 3/2	✓ With reducing sleeve MK 3/2	
Quick-release tool holder Rota-Quick® • Morse taper 3 • with automatic internal cooling • suitable for all machines with drill spindle MK 3 • Application range to 40 mm core drill Ø	18651	-	-	✓	✓	
Quick-release chuck with Weldon arbor for twist drills • Ø 1 - 13 mm	18107	✓	-	-	-	
Quick-release chuck with Morse taper 2 for twist drills • Ø 1 - 16 mm	18008	-	✓	✓ With reducing sleeve MK 3/2	✓ With reducing sleeve MK 3/2	
Quick-release chuck with Morse taper 3 for twist drills • Ø 1 - 16 mm	18009	-	-	✓	✓	
Tool holder AMK-2 - Morse taper 2 for core drills • with Weldon shank • Ø 12 - 60 mm • with automatic internal cooling • suitable for all machines with drill spindle MK 2	18003	-	✓	✓ With reducing sleeve MK 3/2	✓ With reducing sleeve MK 3/2	
Tool holder AMK-2 without internal cooling	18001	-	✓	✓ With reducing sleeve MK 3/2	✓ With reducing sleeve MK 3/2	
Adapter sleeve MK 3/2	18023	-	-	✓	✓	
Tool holder AMK-3 without internal cooling	18002	-	-	✓	✓	
Tool holder AMK-3 - Morse taper 3 for core drills • with Weldon shank • Ø 12 - 60 mm • with automatic internal cooling • suitable for all machines with drill spindle MK 3	18025	-	-	✓	✓	
Tool holder AMK-3 - extended version • with Weldon shank • Ø 12-50 mm, cutting depth 110 mm • with automatic internal cooling • suitable for all machines with drill spindle MK 3	18025L	-	-	✓	✓	
Tool holder AL3 - Morse taper 3 • for core drills heavy duty version • Ø 51-100 mm with keyway with automatic internal cooling	20230	-	-	✓	✓	